BY THE INSPECTING OFFICER TO BE FILLED (Assistant Engineer / Assistant Executive Engineer) : Chinnaya Vidyalaya Talipazamba Vimal Kumar V Assistant : Tali paramba : 2024-2025 permanant bevilding 1)63.00 ×8'54 m (C) F. FF, SF) 5740 × 8.30 (GF, FF, SF) 3) 8·10 ×7.60 (GIF, FF, SF) 4) 21.90 × 8·10 (GF, FF, SF) 5) 26.50 × 8.55 (CIF, FF)

- Name of School
- Name of the Officer 1.
- Location 2.
- Period for which the certificate is issued 3.
- Types of building 4
- Nature of defect if any 5
 - a) Foundation and basement
 - Superstructure b)
 - Doors and windows C)
 - Wood work wrought and put up d)
 - e) Roof
 - Flooring f)
 - Miscellaneous (Cracks if any) g)
- Any major defects noticed which will 6. render the building unsafe in any manner
- Whether maintenance work have been 7. done properly
- Whether the structure is sound or not 8. for conducting classes.

~ ~

cender Normal yes

Kind

weather conduction

1 The Stability of the structure should be examined also with reference to location altitude intensity of Note: wind exposure to flood etc.

Nil

yes

2 Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate.

Certified that the School was inspected by me on 29/05/29 and found to be, fit / unfit to conduct classes for the period (or the reasons stated above.